

OUTDOOR BLEACHERS

BENSON MS: Material, Freight, Labor and tax : \$2562.00

(3) 15' Seat boards
(1) 3 row stringer frame
(15) end caps

Clayton HS: Material, Freight, Labor and tax : \$5764.50

Provide railing and fencing on ramp
Repair ramp to press box
(1) 27' seat board, (1) 27' walk board, (1) 15' seat board
(70) end caps
(25) large alumi stand end caps
Misc Hardware

Clayton MS: Material, Freight, Labor and tax : \$2135.00

Misc hardware, fence ties
(1) 3 row stringer frame
(20) end caps
(1) 15' seat board

Cleveland MS: Material, Freight, Labor and tax : \$1708.00

(2) 21' seat boards
(25) end caps
Fence ties

Four Oaks MS: Material, Freight, Labor and tax : \$1708.00

(20) end caps
(1) 3 row stringer frame

McGees MS: Material, Freight, Labor and tax : \$854.00

(30) end caps

N. Johnston HS: Material, Freight, Labor and tax : \$1708.00

(70) end caps
(2) 15' walk boards
Repair fence railing

CODE COMPLIANCE - riser closures, both banks, visitor side needs aisles and aisle rails:
ADD \$44,963.82

N. Johnston MS: Material, Freight, Labor and tax : \$854.00

(10) end caps
Rework fencing
(5) replacement wheels and pads if bleachers are moved around.

Princeton HS : Material, Freight, Labor and tax : \$2135.00

Wire ties

(2) 15' seat boards

(30) end caps

(15) 6" end caps

Riverwood MS: Material, Freight, Labor and tax : \$1708.00

(1) 15' seat board

(1) 3 row stringer frame

(10) end caps and misc hardware

S. Johnston HS: Material, Freight, Labor and tax : \$427.00

(10) alumina stand end caps

(5) end caps

Replace (1) set of 4 row x 15' - ADD \$17,543.28

Selma MS: Material, Freight, Labor and tax : \$2135.00

(50) end caps

(1) 5 row stringer frame

Misc hardware

Smithfield MS: Material, Freight, Labor and tax : \$854.00

(1) 15' seat board

(10) end caps

Misc hardware

Smithfield Selma HS : Material, Freight, Labor and tax : \$1996.23

(23) end caps

Straighten bent frames

(1) 4 step aisle rail

(1) speedy elbow

Misc Hardware

Soccer - (105) end caps, replace (2) braces, repair one broken frame

W. Johnston HS: Material, Freight, Labor and tax : \$427.00

(20) end caps

Misc hardware

GRAND TOTAL: \$26,975.73

ADDS: \$44,963.82

ADDS: \$17,543.28

INDOOR BLEACHERS

**ALL PRICES ARE AFTER 10% MANUFACTURER'S DISCOUNT HAS BEEN APPLIED.
CONDITIONS OF DISCOUNT: ALL PROVIDED QUOTES ACCEPTED AT THE SAME TIME
PRIOR TO MARCH 15TH 2023.**

Clayton HS: Material, Freight, Labor and tax : \$53,285.40

Replace flex row wheels (108)

Missing (1) P Rail and (2) front row steps

Aux Gym: Provide Code compliant aisles, aisle rails, aisle steps and end rails, (4) 5'-6" ADA cutouts

Cleveland HS: Material, Freight, Labor and tax : \$16,641.40

Replace (1) P Rail arm, (2) flex row frames, (1) PFE gear motor Bank D

Aux Gym: Replace seats (180) and reanchor to the wall

Cleveland MS: Material, Freight, Labor and tax : \$6,333.39

Replace contactor box, Replace (6) P Rails, brackets and sockets

Cooper ES: Material, Freight, Labor and tax : \$4,152.08

Replace (2) end curtains and jack up rows

Corinth Holder ES: Material, Freight, Labor and tax : \$3,210.55

Frame row supports and jack up rows

Apply signage not to sit on in closed position

Micro ES: Material, Freight, Labor and tax : \$35,464.09

Provide Code compliant aisles, aisle rails, aisle steps and end rails, (2) 5'-6" ADA cutouts

Pinelevel ES: Material, Freight, Labor and tax : \$1,407.03

Replace kick board latch brackets and hinges

Princeton HS: Material, Freight, Labor and tax : \$46,815.71

Provide Code compliant aisles, aisle rails, aisle steps, (4) 5'-6" ADA cutouts

Aux Gym: New wiring harness - existing wiring dry rotted. (rewire)

Riverwood MS: Material, Freight, Labor and tax : \$4,672.53

Replace (8) aisle rails brackets

Replace (15) flex row handles and adjust all flex rows

S. Johnston HS : Material, Freight, Labor and tax : \$42,926.46

Replace (24) motor wheels

New wiring harness - existing wiring is dry rotted (rewire)

Aux Gym: (24) flex row pins, (6) P Rails, (6) P Rail brackets

(12) step pads, (21) skirt board bolts

Replace seats (237)

Selma MS: Material, Freight, Labor and tax : \$19,163.92

Provide Code compliant aisles, aisle rails, aisle steps, (1) 5'-6" ADA cutouts

W. Johnston HS: Material, Freight, Labor and tax : \$11,382.80

Replace missing (4) aisle steps, (2) P Rails, (1) P Rail bracket

Aux gym: Provide Code compliant aisles, (6) aisle rails, (6) aisle steps

Smithfield Sr. HS: Material, Freight, Labor and tax : \$66,187.94

Provide Code compliant aisles, aisle rails, aisle steps, end rails.

Wilson Mills ES: Material, Freight, Labor and tax : \$8,503.84

Replace seats (221)

GRAND TOTAL: \$320,147.14